## PRESALTING ROUTES – 2016/17

ROUTE: INDUSTRIAL DEPOT: NEW VALE

**NOTE:** ENSURE THAT ALL ROUNDABOUTS ON ROUTE ARE COMPLETELY GRITTED.

- 1. NOT SALTING: Proceed from Central Depot turn left to roundabout, take 1<sup>st</sup> exit to Heads of the Valleys Road at HoV roundabout take 2<sup>nd</sup> exit to Ebbw Vale roundabout take 1<sup>st</sup> exit to Ebbw Vale, Proceed to New Roundabout take 2<sup>nd</sup> exit A 4047 (Morrison).
- 2. START SALTING: On entering roundabout leave at 3<sup>rd</sup> exit. Proceed around all main routes on Industrial Estate. Exit site on to HoV but return back into Rassau Industrial Estate (to grit entry road from HoV) to Beaufort Wells roundabout, return and exit site on to HoV once again, go into Crown Avenue Industrial Site, proceed

- 11. NOT SALTING: Return to Garden Festival roundabout.
- 12. START SALTING: Proceed along A4046 to Aberbeeg roundabout.
- 13. Mini Gritter (Foreman) Aberbeeg Square
- 14. START SALTING: Proceed along unnamed road to Railway Bridge, proceed under Railway Bridge.
- 15. SALTING: Return along unnamed road to junction of A4046.
- 16. Not Salting Industrial Gritter Take 3<sup>rd</sup> left A467 proceed along A467 to Traffic Lights at Llanhilleth Industrial Estate.
- 17. START SALTING: Turn left at lights, 1<sup>st</sup> right into Industrial Estate, complete Industrial Estate on leaving Industrial Estate, turn right along unnamed road to junction by Llanhilleth Institute. STOP SALTING.
- 18. NOT SALTING: Turn and return to Traffic Lights on A467, turn right at lights, proceed along A467.
- 19. START SALTING: Turn into Glandwr Industrial Estate, proceed to grit whole Estate, exit site on to Commercial Road. STOP SALTING.
- 20. NOT SALTING: At junction on Commercial Road turn left proceed to Aberbeeg roundabout, 2<sup>nd</sup> exit A4046 to roundabout (Old Colliery Site), Cwm.
- 21. START SALTING: Proceed along Marine Street (inc

28. START SALTING: Proceed through Industrial Estate exit on to Newtown roundabout take 2<sup>nd</sup>